

APPENDIX A – BUILDING PHOTOGRAPHS



Photograph 1: View of southwest façade, camera facing northeast.



Photograph 2: View of southwest façade, camera facing north.

USDA – Beltsville Agricultural
Research Center
Demolition of Building 11A



Appendix A - Photographs
December 2020
Beltsville, Prince George's County,
Maryland



Photograph 3: View of perimeter wall and entry ramp on southwest façade, camera facing north.



Photograph 4: View of southwest façade, camera facing northeast.



Photograph 5: View of main entry stair at intersection of southwest and northwest façade, camera facing northeast.



Photograph 6: View of northwestern façade, camera facing east-southeast.



Photograph 7: View of bay entry on northwestern façade, camera facing southeast.



Photograph 8: View of air conditioning unit on northwestern façade, camera facing south.



Photograph 9: View of brick wall shielding utility machinery on the northwest façade, camera facing south.



Photograph 10: View of northeast façade, camera facing south-southeast.



Photograph 11: View of intersection of southeast and northeast façade, camera facing southwest.



Photograph 12: View of southeast façade, camera facing northwest.



Photograph 13: View of courtyard, camera facing west.



Photograph 14: View of courtyard, camera facing southeast.

USDA – Beltsville Agricultural
Research Center
Demolition of Building 11A



Appendix A - Photographs
December 2020
Beltsville, Prince George's County,
Maryland



Photograph 15: View of main entry, camera facing northeast.



Photograph 16: View of signage and cornerstone at main entrance, camera facing northeast.



Photograph 17: View of covered entrance to Building 11A.



Photograph 18: View of parking lot associated with Building 11A, camera facing northwest.



Photograph 19: View of pumping station associated with Building 11A, camera facing west.



Photograph 20: Partial view of rooftop machinery and entrance, camera facing southeast.



Photograph 21: General interior overview of Building 11A.



Photograph 22: General interior overview of Building 11A.



Photograph 23: General interior overview of Building 11A.



Photograph 24: General interior overview of Building 11A.



Photograph 25: General interior overview of Building 11A.




Photograph 26: General interior overview of Building 11A.



Photograph 27: General interior overview of Building 11A.



Photograph 28: General interior overview of Building 11A.



Photograph 29: General interior overview of Building 11A.



Photograph 30: General interior overview of Building 11A.



Photograph 31: General interior overview of Building 11A.



Photograph 32: General interior overview of Building 11A.



Photograph 33: General interior overview of Building 11A.




Photograph 34: General interior overview of Building 11A.



Photograph 35: General interior overview of Building 11A.



Photograph 36: General interior overview of Building 11A.



Photograph 37: General interior overview of Building 11A.



Photograph 38: General interior overview of Building 11A.

