Environmental Assessment BARC Demolition of 22 Buildings	· ·	January 2020
	APPENDIX A – PHOTO	3RAPHS







Photo 01: Building 053, north side (front)



Photo 03: Building 053, inside



Photo 02: Building 053, west side and attached greenhouse at back



Photo 04: Building 053, inside of greenhouse hallway







Photo 05: Building 177B, east side



Photo 07: Building 177B, west side



Photo 06: Building 177B, south side



Photo 08: Building 177B, north side





Photo 09: Building 288A, north (front) and west sides



Photo 11: Building 288A, view of side



Photo 10: Building 288A, view of window on side

(a) Access to Building 288A is provided by a facility road accessible only by authorized personnel and was not accessible during the site visit conducted on October 22-24, 2019. Photos of Building 288A were included in a Determination of Eligibility submitted to the Mary land Historical Trust (MHT on January 31, 2017.

Building 327A



Photo 12: Building 327A, east side (front)



Photo 14: Building 327A, east side (front)



Photo 13: Building 327A, east side (front)



Photo 15: Building 327A







Photo 16: Building 435A, front

Photo 17: Building 435A, front and adjacent cattle pen







Photo 18: Building 465, north and west sides



Photo 20: Building 465, inside of hall between main building and greenhouses



Photo 19: Building 465, greenhouses attached at back



Photo 21: Building 465, large tank and electrical infrastructure, southwest side



Building 470A



Photo 22: Building 470A, northeast corner, adjacent to Building 470



Photo 24: Building 470A, greenhouses attached at south side (back)



Photo 23: Building 470A, north side



Photo 25: Building 470A, inside of greenhouse







Photo 26: Building 470C, east side (front), garage door lock and sign

Photo 27: Building 470C, east side (front)



Photo 28: Building 470C, east side (front)





Photo 29: Buildings 470AA – 470JJ, north side (front) of greenhouses



Photo 31: Building 470GG, inside



Photo 30: Building 470HH, north side (front)



Photo 32: Buildings 470AA – 470JJ, representative photo of inside greenhouse







Photo 33: Building 471, remains



Photo 35: Building 471, remains



Photo 34: Building 471, remains



Photo 36: Building 471, remains





Photo 37: Building 1145, north (front) and west sides



Photo 39: Building 1145, west side



Photo 38: Building 1145, south (back) and east sides



Photo 40: Building 1145, inside





Photo 41: Building 1204, east (front) and north sides



Photo 43: Building 1204, west (back) side



Photo 42: Building 1204, south side



Photo 44: Building 1204, inside





Photo 45: Building 1206, east (front) and south sides



Photo 47: Building 1206, entrance



Photo 46: Building 1206, north side




Photo 48: Building 1206, inside